


M/019/005

POTENTIAL FOR BRINE SEEPAGE ALONG ROCK FRACTURES.
BRINE LAKE STORAGE AREA.
CANE CREEK MINE, GRAND COUNTY, UTAH

MOAB SALT, INCORPORATED
MOAB, UTAH

Prepared by
EARTHFAX ENGINEERING, INC.
SALT LAKE CITY, UTAH

JUNE 26, 1989



Moab Salt Incorporated
Moab, Utah


Brine Lake Seepage Report
June 26, 1989

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
1.0 INTRODUCTION	1
2.0 METHODS OF DATA COLLECTION	4
2.1 SURFICIAL GEOLOGY	4
2.2 VLF-EM	4
3.0 RESULTS AND DISCUSSION	9
3.1 RESULTS OF BRINE SEEP SURVEY	9
3.2 VLF-EM	12
3.3 DISCUSSION	22
4.0 REFERENCES	24

LIST OF FIGURES

	<u>Page</u>
Figure 1. General Location of the Cana Creek Mine	2
Figure 2. Map of Brine Lake and Surrounding Area	3
Figure 3. Map Showing Faults Which Intercept the Brine Lake Area . .	5
Figure 4. Map Showing Locations of VLF-EM Lines	6
Figure 5. Southeast View of Brine Seepage in Canyon North of Brine Lake	10
Figure 6. Northwest View of Brine Seepage in Canyon North of Brine Lake	10
Figure 7. Northwest View of Fault C in Canyon North of Brine Lake	11




Moab Salt Incorporated
Moab, Utah

Brine Lake Seepage Report
June 26, 1989

TABLE OF CONTENTS (Continued)

Figure 8. Southeast View of Brine Seepage Associated with Fault B at the South Abutment of the Brine Lake Dam . . .	11
Figure 9. Northwest View of Brine Seepage Associated with Fault B at the South Abutment of the Brine Lake Dam . . .	13
Figure 10. North View of Brine Seepage Away From Fault B Below Brine Lake Dam	13
Figure 11. East View of Arroyo Below Brine Lake Dam	14
Figure 12. VLF-EM Profile of Line 1	15
Figure 13. VLF-EM Profile of Line 2	16
Figure 14. VLF-EM Profile of Line 3	17
Figure 15. VLF-EM Profile of Line 4	18
Figure 15. VLF-EM Profile of Line 4 (Continued)	19



Moab Salt Incorporated
Moab, Utah

Brine Lake Seepage Report
June 26, 1989

POTENTIAL FOR BRINE SEEPAGE ALONG ROCK FRACTURES,
BRINE LAKE STORAGE AREA,
CANE CREEK MINE, GRAND COUNTY, UTAH

1.0 INTRODUCTION

This report presents results of a surficial geologic field investigation and a very-low-frequency electromagnetic (VLF-EM) survey of bedrock fractures at the Cane Creek Mine, Grand County, Utah (Figure 1). The emphasis of this report is directed toward a study of fractures which underlie Moab Salt's brine storage lake and those fractures associated with the brine lake dam abutments and spillway (Figure 2). This study was undertaken in response to written comments prepared (1/28/88) by the Utah Division of Oil, Gas and Mining (DOGM) concerning the potential of fractures which underlie the brine lake to transmit brine to off-site areas. Moab Salt, in written response (5/18/88) to DOGM comments, agreed to undertake additional study of faulted and fractured bedrock in the vicinity of the brine lake area to evaluate the potential for brine seepage toward the Colorado River.

This report is divided into four sections including this introduction. Sections 2 presents methods of data collection; whereas, Section 3 presents results and discussion of the investigation. Referenced literature is documented in Section 4.



*M/019/005*

MOAB SALT, INC.

P.O. Box 1208, MOAB, UTAH 84532 • OFFICE 801-259-7171 • FAX 801-259-7100

FAX MEMO

To:

TONY GALLEGOS

From:

Rick York
General Manager
PCS Potash - Moab Division

Number of Pages (including cover page):

5

Message:

JUNE 26, 1989 REPORT INFO -EARTHFAK ENGINEERING, INC.

POTENTIAL FOR BRINE SEEPAGE
ALONG ROCK FRACTURES